


2019 BMW X2 xDrive 28i AWD (F39) L4-2.0L Turbo (B460)

Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Service and Repair > Procedures

TIGHTENING THE OIL FILTER CAP [REP-TAT-P-1142-02-F46_B38_4]

Tightening the oil filter cap

REP-TAT-P-1142-02-F46_B38_4



- Feed in and install the oil filter cover (1).
- Tighten oil filter cover (1) on hexagon head (2).

Tightening torques

Oil filter cover on oil filter housing

S88.5 x 3	New sealing ring lightly oiled.
tightening torque	27Nm

BMW Engine Oil Service Without Supplementary Service		
Back To Step 8	Step 9 of 14	Go To Step 10