


2019 BMW X2 xDrive 28i AWD (F39) L4-2.0L Turbo (B46O)
Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Service and Repair > Procedures

CLOSING THE SERVICE FLAP IN THE FRONT UNDERBODY PROTECTION [REP-TAT-P-5147-07-F46_B38]

Closing the service flap in the front underbody protection

REP-TAT-P-5147-07-F46_B38



- Close the service flaps (1) in the front underbody protection in the arrow direction.

BMW Engine Oil Service Without Supplementary Service		
Back To Step 10	Step 11 of 14	Go To Step 12