

2019 BMW X2 xDrive 28i AWD (F39) L4-2.0L Turbo (B460)

Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Service and Repair > Procedures

INSTALLING THE OIL FILLER CAP [REP-TAT-P-1112-02-F46_B38]

Installing the oil filler cap

REP-TAT-P-1112-02-F46_B38



- Close oil filler cap (1).

BMW Engine Oil Service Without Supplementary Service		
Back To Step 12	Step 13 of 14	Go To Step 14