


2019 BMW 540i Sedan (G30) L6-3.0L Turbo (B58M)

Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Engine Oil > Service and Repair > Procedures

TIGHTENING THE OIL FILTER CAP [REP-TAT-P-1142-02-G11_1]

Tightening the oil filter cap

REP-TAT-P-1142-02-G11_1



- Tighten the oil filter cover (1).

Tightening torques

Oil filter cover to oil filter module

O-ring lightly oiled. **Tightening torque** 25Nm

Engine Oil Service		
Back To Step 5	Step 6 of 11	Go To Step 7