

2019 BMW 540i Sedan (G30) L6-3.0L Turbo (B58M)
Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Engine Oil > Service and Repair > Procedures

RECOMMENDATION: CARRYING OUT AN ELECTRONIC OIL MEASUREMENT [REP-TAT-P-1100-05-OTTO_1]

Recommendation: Carrying out an electronic oil measurement

REP-TAT-P-1100-05-OTTO_1

Prerequisite

Vehicle in horizontal position.

 TECHNICAL INFORMATION

Please comply with instructions in Owner's Manual.

Carry out an electronic oil measurement.
Top up motor oil if necessary.

Engine Oil Service		
Back To Step 7	Step 8 of 11	Go To Step 9