


2019 BMW 540i Sedan (G30) L6-3.0L Turbo (B58M)

Vehicle > Engine, Cooling and Exhaust > Engine > Engine Lubrication > Engine Oil > Service and Repair > Procedures

RELEASING THE OIL FILTER COVER [REP-TAT-P-1142-01-G11_1]

Releasing the oil filter cover

REP-TAT-P-1142-01-G11_1



- Loosen the oil filter cover (1).

Engine Oil Service		
Back To Step 1	Step 2 of 11	Go To Step 3